USGS
science for a changing world

Before and After Hurricane Ike Images–Delacroix, Louisiana
(Landsat Enhanced Thematic Mapper+ and Thematic Mapper Satellite Imagery)



September 7, 2008 Landsat 7 ETM+

The diagonal black lines crossing the image are caused by malfunction of Landsat 7's Scan Line Corrector (SLC-off).



October 1, 2008 Landsat 5 TM

Surge-removed floating and submerged aquatic vegetation zone. Both Hurricane Gustav's and Ike's cumulative surges appears to have removed significant amounts of acquatic and other transitory vegetation that characterized the area between the Delacroix and the Mississippi River after the surge impacts of Hurricanes Katrina and Rita in 2005. The blue cast of the October TM 5 image is casued by salt-burning of fresh and intermediatev marsh vegetation from the combined surges.

Scale 1:85,000

2 0 2 4 6 8 Kilometers

DRAFT DS XXX

U.S. Department of the Interior
U.S. Geological Survey

Preliminary visual examination Ocober 1, 2008.

Contact: John Barras
barrasj@usgs.gov

Image Sources:
Landsat TM and ETM+ satellite imagery is provided by the USGS EROS Data Center.
Bands 4 (near-ir), 5 (mid-ir), and 3 (visible red) are displayed.